DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Arnold Schwarzenegger, Governor

Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-004070

Address: 333 Burma Road **Date Inspected:** 07-Oct-2008

City: Oakland, CA 94607

OSM Arrival Time: 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes N/A No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** OBG Side and Edge Plate

Summary of Items Observed:

Bay 4:

This QA observed ZPMC/NDE Su Hei and Cai Xin Xin perform MT on the following plates. This QA also performed VT prior 10% MT on these same plates;

- a) SP312A OBG side plate
- b) EP32B OBG edge plate
- c) SP721B OBG side plate
- d) SP483B OBG side plate
- e) SP615B OBG side plate
- f) SP535B OBG side plate
- g) SP313A OBG side plate
- h) SP366A OBG side plate

These plates have been green tagged by ABF/QA after finding it acceptable by all concerned parties. For more information, please see my TL-6028 on this day.

Summary of Conversations:

No significant conversation ocurred today.

Comments

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Joshua Ishibashi, (858) 232-7081, who represents the Office of Structural Materials for your project.

| Inspected By: | Lizardo, Joselito | Quality Assurance Inspector |
|---------------|-------------------|-----------------------------|
| Reviewed By: | Cuellar,Robert | QA Reviewer |